

IVI-EG

5.Aug.2021
TOYOTA MOTOR CORPORATION
Woven Alpha, Inc.

Technical Discussions Plan

■ Plan / History

#	date	Discussion Topics
1	Dec. 8, 2020	Kickoff, LifecycleManagement,
2	Jan. 7, 2021	LifecycleManagement, HelathMonitoring, + “HAL”, <i>Yocto Recipe</i>

8	May 27, 2021	Requirement Spec Review 2(Power State Management + α), Flutter? , TBD
9	June 10, 2021	Requirement Spec Review 3(Service Launch/Termination, System Logging Support)
10	June 15, 2021 Virtual Workshop	Requirement Spec Review 4(Use cases for each function), ...
11	June 24, 2021	Requirement Spec Review 5(Power State Management), ...
12	July 8, 2021	Requirement Spec Review 6(Service Launch / Termination, Service Failure Detection), ...
13	Aug 5, 2021	Requirement Spec Review 7(Service Launch / Termination, Service Failure Detection, System Logging Support, Backup Data Management, Vehicle Parameter Configuration),

Requirement Spec activity part1 (10min)

What to explain today...

- I explained the following requirements specification at the last meeting
 - Services Launch / Termination :
<https://confluence.automotivelinux.org/pages/viewpage.action?pageId=44826721>
 - System Failure Detection and Procedure :
<https://confluence.automotivelinux.org/display/IVIPR/4.3+System+Failure+Detection+and+Procedure>
 - I got a few additional points.
 - Services Launch / Termination
 - Service launch with power state transition / Service termination with power state transition
 - Static setting and Dynamic setting
 - System Failure Detection
 - Additional requirement: The frequency with which the Detector checks the service should be configurable.

Requirement Spec activity part2 (45min)

What to explain today...

- The additional requirements specification
 - System Logging Support :
<https://confluence.automotivelinux.org/display/IVIPR/4.4+System+Logging+Support>
 - Backup Data Management :
<https://confluence.automotivelinux.org/display/IVIPR/4.5+Backup+data+management>
 - Vehicle Parameter Configuration
<https://confluence.automotivelinux.org/display/IVIPR/4.6+Vehicle+Parameter+Configuration>
 - The Message Notification function previously described is not an in-vehicle specific function, so we defined not to list it up as a required specification for product.
- For 3 requirements, if you have any additional points, please comment on the confluence page or contact me **by August 18(Wed)**. This slide is on the confluence page : <https://confluence.automotivelinux.org/display/IVIPR/Minutes>