




VIRTIO features progress

- virtio-scmi finalizing driver
- virtio-video decoder, encoder, and camera with hardcoded settings
 - Noticed that HW video decoding is not available in AGL: <u>SPEC-4029</u>
 - Provided review for videplayerapp:
 https://gerrit.automotivelinux.org/gerrit/c/apps/videoplayer/+/26334
 - Checking camera application: arroundview (v4l2 based), camera-gstreamer
- virtio-can
 - SPEC-3776 AGL RH boots with CAN errors
- virtio-bt
 - AGL Reference Hardware availability with BT



Other tasks

- 1. Triggering SCIF download remotely: idea is to solder relay.
- 2. Building firmware from AGL workspace: changes by Scott/Vasyl merged, need to fix missing 0001-rcar_gen3-plat-Delete-FDT-function-calls.patch